
| City of Baltimore Wet<br>Smoke and Dyed   | Page 1 of 1                           |  |
|---|---------------------------------------|--|
| Sewershed: Gwynns Falls                   | Company: Savin                        | Date: 9/22/2009                              |
| Test to be performed:  Smoke Dyed Water X | Ground Condition:  Dry ✓ Damp ☐ Wet ☐ | Supervisor: <u>JAW</u>                       |
| Manhole_ID: S08G001MH                     | Test ID: <u>D1032-006001</u>          | Notification Made: NA (Residents, Fire, 311) |

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



| Defect Loc | Obs_ClockFrom | Obs_ClockTo | Observation      | Obs_Remarks            |
|------------|---------------|-------------|------------------|------------------------|
| 0          |               |             | Start of Survey  |                        |
| 0          |               |             | Manhole          | S08G001MH              |
| 0          |               |             | Water Level      |                        |
| 2          |               |             | Dye Test Visible | DYE SEEN AT CONNECTION |
| 57.5       |               |             | Abandoned Survey | DYE TEST IS COMPLETE   |